

i leid Observation Neport Number: Monnstown, 193	Field Observation	Report	Number:	Morristown,	NJ
--	--------------------------	--------	---------	-------------	----

To:	David Levo	Today's Date	: 1/20/2012
From:	Edward Hesselbacher	Sheet:	1 of 2 Date of Visit: 12/7/10
Project:	WPU Academic Zone Master Plan	Trade:	Electrical
Project No.:	WPU01000	Site Contact:	

General

- a) The fire alarm systems for all associated buildings were installed approximately ten years ago.
- b) Each building has a fire alarm connection to a central monitoring location on-campus.
- c) The campus fire alarm system is manufactured by Simplex.
- d) The electrical utility serving the university is PSE&G.

Coach House

- 1. Electric service is at 120/208V with a rated ampacity of 400A. The service originates from the switchgear in the facilities building where a meter is provided.
- 2. The main electric service terminates on a wiring trough. From the wiring trough there is a distribution panel that serves additional panels as well as a 250 Amp UPS system that is not used.
- 3. The electric service is in excess of 50 years old. Facilities services reports difficulties replacing parts for most of the equipment.
- 4. The main service equipment is in a set-back closet in a room which makes maintenance challenging.

Hunziker Hall - Wing

- 1. The buildings are served by an exterior pad mounted 1500KVA transformer. The building receives a 277/480V service with a rated ampacity of 2500A.
- 2. The main switchboard lineup includes a 750KVA transformer which steps down the voltage from 277/480V to 120/208V. The switchboard lineup was installed less than 10 years ago and is in good condition.
- 3. From the switchboard lineup there is distribution to panels throughout the building. With the exception of the equipment in the computer lab, the equipment is very old.
- 4. There is a natural gas powered 150KVA emergency generator which serves the computer lab. The generator was installed in 2004 and is in good condition.
- 5. A Simplex 4020 fire alarm system serves the building with horn/strobes, pull stations and photo electric type smoke detectors. The fire alarm system is in good condition.

 $H:\studio-7\46490.00\ William\ Paterson\ Univ\ MP\Archives\WPU\Out\2012-01-20\ Revised\ MEP\ Field\ Observations\William\ Patterson\ University_Field\ Obs\ Rpt_electrical.doc$

Tel: 212.921.2300

Fax: 212.556.3262

www.syska.com



Field Observation Report	Number: Mor	rristown, NJ
---------------------------------	-------------	--------------

To:	David Levo	Today's Date:	1/20/2012
From:	Edward Hesselbacher	Sheet:	2 of 2 Date of Visit: 12/7/10
Project:	WPU Academic Zone Master Plan	Trade:	Electrical
Project No.:	WPU01000	Site Contact:	

Raubinger Hall

- 1. The building is served by an exterior 700KVA pad mounted utility transformer.
- 2. The service is at 120/208V with a rated ampacity of 3000A.
- 3. The fire alarm system is a fully addressable Simplex 4020 system
- 4. The electric distribution was replaced on the 4th floor 5 years ago and is in good condition.
- 5. Floors 1, 2 and 3 are old and in poor condition.

Shea Center for Performing Arts

- 1. The building is served by an exterior 500KVA pad mounted utility transformer.
- 2. The service is at 120/208V with a 2000A rating.
- 3. There is a 30KVA isolation transformer to provide clean power to the performance area.
- 4. The main service and performance area are in good condition having been recently replaced.
- 5. The electric service in the rest of the building is in poor condition.
- 6. The fire alarm system is a Simplex 4010 system. Facilities recommends replacing the system with a 4100 system.

Wightman Gym

- 1. Electric service is at 120/208V with a rated ampacity of 1200A. The service originates from the switchgear in the facilities building where a meter is provided.
- 2. The electric service is old and in poor condition. Facilities experiences difficulties replacing parts.
- 3. All power to the pool area has been provided with Ground Fault Protection.

Tel: 212.921.2300 Fax: 212.556.3262

www.syska.com

4. The fire alarm system is a Simplex 4010 system. Facilities recommends upgrading to a system with addressable photo-electric type detectors.